

(SUBMIT IN TRIPLICATE)

Indian Agency Ute

Cont. 14-20-604-124

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Co. Lease No. 234674

<b>X</b>		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____	<b>Temporary Abandonment</b> _____	<b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico, July 8, 1960

Ute Tribe of Indians "U"

Well No. 2 is located 660 ft. from N line and 1980 ft. from W line of sec. 25

NE 1/4 of NW 1/4, 25  
(1/4 Sec. and Sec. No.)

31 North 15 W  
(Twp.) (Range)

104 M  
(Meridian)

Verde-Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)


(State or Territory)

The elevation of the derrick floor above sea level is 5479 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well temporarily shut in. Possible remedial work being studied.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 2347, Hobbs, New Mexico

ORIGINAL  
SIGNED: R. R. ALWORTH

By \_\_\_\_\_

Title Agent

