

(SUBMIT IN TRIPLICATE)

Indian Agency Ignacio

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Ute Indian

Lease No. 14-20-60-20

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 17, 1960

Ute Indian

Well No. 10-1 is located 660 ft. from S line and 660 ft. from E line of sec. 30

Section 30

(1/4 Sec. and Sec. No.)

T-12E

(Twp.)

R-14W

(Range)

N.M.P.M.

(Meridian)

Verde-Gallup

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 5403 ft. S.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 5/15/60


Set 3 jct., 95' of 7 1/8" surface casing, landed at 100' with 125 sacks cement
Tested casing with 900# pressure for 30 minutes.

No leaks.

Spilled cement plug 5/16/60

Tested casing with 900# pressure for 30 minutes

No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Acme Oil and Gas Company

Address Box # 106, Farmington

New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By Joe C. Salmon
District Superintendent

Title