



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP-878115
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS **RECEIVED**
AUG 22 1957

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 14, 1957

Well No. Greater 6 is located 1630 ft. from S line and 1630 ft. from W line of sec. 20

SE/4, Section 20
(1/4 Sec. and Sec. No.)

T-11-N, R-11-W
(Twp.) (Range)

R.M.P.M.
(Meridian)

Elanco
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6036 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

July 31, 1957 set 4739' of 7 5/8" casing at 4740' - DV Seal set at 2695 cemented with 175 sacks each stage. Drilled cement August 2, 1957. Stubbed hole dry. Tested for 2 hours with 900# pressure, pipe O.K. Drilled to 5105'. August 3, 1957 set 468' of 5 1/2" liner to 5104' with 100 sacks cement. Drilled cement. Stubbed hole dry. Tested for 2 hours with 900# pressure, pipe O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AMSC OIL & GAS COMPANY

Address P.O. Box 786

Farmington, New Mexico

By Joe C. Salmon
Joe C. Salmon
Title District Superintendent