


(SUBMIT IN TRIPLICATE)

Form approved.
Budget Bureau No. 42-R359.4.

Indian Agency Ute Mountain
Tribal Lands

Allottee _____
Contract 14-20-604-87
Lease No. _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 14, 1964

Ute Mountain Tribe "A"
Well No. 4 is located 1980 ft. from [S] line and 1980 ft. from [E] line of sec. 21

SE/4 Section 21 (4 Sec. and Sec. No.) 31 N (Twp.) 15 W (Range) MMN (Meridian)

Verde Valley (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation of the deckline above sea level is 5626 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We request permission to remove all equipment, pull casing, plug and abandon well.

1. Plug 1850 - TD @ about 1928
 2. 100' plug on 5 1/2" stub
 3. Plug 650 - 750 across top of Mancos
 4. Plug 85' - 135' across 8 5/8" shoe
 5. 105 x at surface w/marker
- Heavy mud between plugs.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. & S. Casing Pulling Service

Address Box 778

Craig, Colorado

By William J. Rippey
Title partner