

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mountain

Tribal Lands

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allettes  
Contract No. 14-33-406-87  
Lease No. 14-33-406-87


SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<b>I</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

19 Feb, 1964

Ute Mountain Tribe "EA"  
Well No. 6 is located 2310 ft. from [S] line and 330 ft. from [E] line of sec. 22

Section 22 31 N 15 W 14N  
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Verde Gallup San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5595 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Run plug from 2331' to 2200'.
  2. Shot & recovered 1700' of 5 1/2" casing.
  3. Run 100' plug in & across 5 1/2" casing stub.
  4. Run 100' plug across top of Hanson 950' to 1050'.
  5. Run 50' plug from 75' to 125' on 8 5/8" shoe.
  6. Run 10 sack at surface and erected regulation marker.
  7. Heavy mud was run between plugs.
  8. All the equipment has been removed from the location.
- The location was cleaned up.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company G & S Casing Service

Address Box 778

Craig Colorado.

By W. J. Rippy Jr.

Title Operator