

State

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Ute Mountain
Tribal
Lease No. **14-20-604-83**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	RECEIVED AUG 1 1962 D
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

July 31, 19**62**

Well No. **1 Ute** is located **1980** ft. from **[N]** line and **2050** ft. from **[E]** line of sec. **22**

NE/4 Sec. 22

(1/4 Sec. and Sec. No.)

31 N.

(Twp.)

14 W.

(Range)

NMPM

(Meridian)

Verde-Gallup

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

ground level

The elevation of the ~~XXXXXX~~ above sea level is **5737** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 4 joints 8-5/8 casing 116.68'. Set at 126', cemented with

100 sacks regular cement. Plug down 8:45 A.M., July 30, 1962.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WALTER DUNCAN**

Address **Post Office Box 137**

Durango

Colorado

By **Raymond T. Duncan**

Title _____