

Sec. 21

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**

|    |  |  |  |
|----|--|--|--|
| 22 |  |  |  |
|    |  |  |  |
|    |  |  |  |
|    |  |  |  |

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Allottee **14-20-604-83**  
Lease No. **Ute Mountain**

## SUNDRY NOTICES AND REPORTS ON WELLS

|  |  |   |          |
|--|--|---|----------|
| NOTICE OF INTENTION TO DRILL.....                  |  | SUBSEQUENT REPORT OF WATER SHUT-OFF.....        | <b>X</b> |
| NOTICE OF INTENTION TO CHANGE PLANS.....           |  | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |          |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....    |  | SUBSEQUENT REPORT OF ALTERING CASING.....       |          |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL..... |  | SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....  |          |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....       |  | SUBSEQUENT REPORT OF ABANDONMENT.....           |          |
| NOTICE OF INTENTION TO PULL OR ALTER CASING.....   |  | SUPPLEMENTARY WELL HISTORY.....                 | 1959     |
| NOTICE OF INTENTION TO ABANDON WELL.....           |  |   |          |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 30, 1959

Well No. **2** is located **1980** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **21****N1/4 Sec. 21**  
(1/4 Sec. and Sec. No.)**T-31N**  
(Twp.)**R-14W**  
(Range)**N.M.P.M.**  
(Meridian)**Verde Gallup**  
(Field)**San Juan**  
(County or Subdivision)**New Mexico**  
(State or Territory)**G.L.**The elevation of the ~~derick~~ floor above sea level is **9673** ft. **Int.**

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 2760' of 5 1/2" O.D. 14# J-55 casg. @ 2770' cemented with 250 sks. 8% Gel  
1/2# floccule per sk. 1/30 sks. neat. Did not circulate, PD 4 A.M. 3-27-59  
ran temp. survey top of cement @ 990' WOC 24 hrs. Tested 5 1/2" casg. w/  
1000# for 30 minutes held OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Magnolia Petroleum Company**Address **P. O. Box 2406****Hobbs, New Mexico**

By

Title

**District Superintendent**