

PUBCO

POST OFFICE BOX 869 • ALBUQUERQUE, NEW MEXICO 87103 • TELEPHONE (505) 842-1940

September 21, 1971

Oil Conservation Commission
State of New Mexico
1000 Rio Brazos Road
Aztec, New Mexico 87410


Re: Ute Mt. #19-7
G-19-31N-14W
San Juan County, New Mexico

Gentlemen:

As per your request of September 15, 1971, enclosed is a copy of the Subsequent Report of Abandonment on the captioned well filed with the USGS December 27, 1961.


If additional information is needed, please advise.

Very truly yours,



(Mrs.) Christena Marsland
Secretary to J. C. Johnson
Vice President Production

/cm



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYIndian Agency Mountain Ute
Agency San Juan, Colorado
Allottee Mountain Ute Tribe
Lease No. 11-20-01-100

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Aztec, New Mexico December 27, 1962Well No. 10-7 is located 2000 ft. from N line and 2000 ft. from E line of sec. Section 10
(1/4 Sec. and Sec. No.)30 North 10 West
(Twp.) (Range)T11N R10W
(Meridian)Vendo-Salinas
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)


Ground

The elevation of the derrick floor above sea level is 5100 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Moved on rig; pulled rods; tubing stuck; pumped 50 sack plug down tubing; tubing parted; pulled 9 jts. tubing; cut pipe at 200 feet; set 15 sack plug over stub; pulled 6 jts. casing; set 10 sack plug over end of surface; set 3 sack plug with marker on surface. Plugged and abandoned 11-29-61.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company FURCO ENTERPRISES CORP.Address 101 West CanadaAztec, New MexicoBy Don E. ThompsonTitle Field Foreman