


(SUBMIT IN TRIPLICATE)

Indian Agency Ute IndianUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 14-20-604-82

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 29, 19 58

Ute-Indian 1-E

Well No. / is located 1980 ft. from N line and 660 ft. from W line of sec. 20

SW/NW, Section 20

(¼ Sec. and Sec. No.)

T-31-N, R-14-W

(Twp.)

(Range)

N.M.P.M.

(Meridian)

Verde-Gallup

(Field)

San Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 5643 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded April 24, 1958. Set 95' of 10 3/4" casing at 96' with 100 sacks cement. Tested for 30 minutes with 500# pressure, no leaks. Drilled cement plug April 26, 1958. Tested for 30 minutes with 500# pressure, no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AZTEC OIL & GAS COMPANYAddress P O Box 786Farmington, New MexicoBy /s/ Joe C. SalmonTitle District Superintendent