Land Office _____
Lease No. ____ - 077 51
Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, _____, 19 59

Well No. __5__ is located __1320__ ft. from N line and __1460__ ft. from E line of sec. __21__

SE/SE, Section 21 T-31N R-15W		N.M.P.M.
(¼ Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)

Blanco-Mesaverde	San Juan	New Mexico
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is __6245__ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD - 5185. Ran 203 jts., 5178' of 7" production casing, landed at 5185. Cemented with 75 sacks cement. Plug down - 6/30-59. Top of cement at 4100'. Drilled cement plug 7/1/59. Cleaned out to 5159. Swabbed dole by, tested for 2 hours with 50# pressure. Pipe Okay!

ILLECIBLE

RECEIVED
JUL 15 1959
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ____Aztec Oil and Gas Company____

Address ____P. O. ____

____Aztec, New Mexico____

By ORIGINAL SIGNED BY JOE C. SALMON
____Joe C. Salmon____

Title ____District Superintendent____