

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office **Santa Fe**
Lease No. **87 077652**
Unit **East**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	XX
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 19 62

East

Well No. **11** is located **1150** ft. from **[N]** line and **220** ft. from **[E]** line of sec. **24**

NE Section 24

(1/4 Sec. and Sec. No.)

Basin Dakota

(Field)

T-31N

(Twp.)

R-12W

(Range)

San Juan

(County or Subdivision)

N.M.P.M.

(Meridian)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **6028** ft. **G.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 8/17/62


Ran 10 jts., 308' of 8 5/8" casing, landed at 322' with 250 ex. cnt.

Tested with 500# pressure for 30 minutes. No leaks.

Drilled cement 8/19/62

Tested with 500# pressure for 30 minutes

No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Artec Oil and Gas Company**

Address **Drawer # 570**

Farmington, New Mexico

By **ORIGINAL SIGNED BY JOE C. SALMON**
Joe C. Salmon

Title **District Superintendent**