


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Mountain Ute
Agency, Ignacio, Colorado
Allottee Mountain Ute Tribe
Lease No. 14-02-02-119



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artes, New Mexico December 9, 19 57

Well No. 19-3 is located 605 ft. from N line and 1835 ft. from W line of sec. 19
Sec. 19 (4 Sec. and Sec. No.) 11N (Twp.) 14W (Range) S.N.P.M. (Meridian)
Yuma-Valley (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ground level above sea level is 7637 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-5-57.

CASING DETAILS:

Run 3 jts., 9 1/2', 8 1/2', 8 1/2' and 8 1/2' OD, 100 lb. casing; landed at 104' from ID.

Cemented with 100 sac regular cement, 25 bags; good circulation, about 6 sac cement returns. WOB at 12:20 A.M. 12-6-57.

Tested to 1000 pounds. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company FURCO FERTILIZER CORPORATION

Address 106 West Chisler

Artes, New Mexico

By E. E. Russell, Jr.

Title Mgr. Prod. Dept.



