

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **14-20-004-83**

Lease No. **Ute Mountain**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

August 1, 1960

Well No. **11** is located **660** ft. from **N** line and **510** ft. from **E** line of sec. **21**

NE/4 Sec. 21 (1/4 Sec. and Sec. No.)
Verde Gallup (Field)
31N (Twp.)
14N (Range)
NMPM (Meridian)
San Juan (County or Subdivision)
New Mexico (State or Territory)

The elevation of the ~~curtain-floor~~ **ground level** above sea level is **5707** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 8:00 pm 7/29/60.

Set 3 jts. of 8-5/8" cas. @ 104' w/80 sax + 2% CaCl₂.

Plug down 4:45 am 7/30/60. Tested w/800 psi for 30 min.; o.k.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company **Severy Mobil Oil Company, Inc.**

Address **Box 3371**

Durango, Colorado

By **P. M. Barry**

Title **Dist. Prod. Supt.**