

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency NavajoAllottee Chimney RockLease No. 2-149-1st-7552

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 12

1957

Well No. 1 is located 2000 ft. from N line and 2000 ft. from W line of sec. 22
SE SW 4 of 22 T-21-N R-17-W WPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan County New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the ground above sea level is 5242 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


A total depth of 5316 feet was reached in an 8 3/4 inch hole on March 9, 1957. On March 9, 1957 verbal permission was obtained from Mr. J. W. Long of the U. S. Geological Survey office in Farmington, New Mexico to plug and abandon this well in the following manner: 25 sacks cement from 7000 to 7900 feet, 25 sacks cement from 6000 to 6900 feet, 25 sacks cement from 5000 to 5900 feet, 25 sacks cement from 2500 to 2400 feet, 25 sacks cement from 1450 to 1550 feet, 15 sacks cement from 670 to 720 feet, and 10 sacks cement in collar. An appropriate sign and marker will be placed at well site. The location will be restored as nearly as possible to its original status and the U. S. Geological Survey office in Farmington, New Mexico will be notified of the completion date. No commercial shows of oil or gas were encountered during the drilling of this well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Reynolds Mining Corporation
Oil and Gas Division
 Address 1524 East Ninth Street
Post Office Box 1328
Durango, Colorado

901

By C. J. Knudsen, Jr.
 Title District Petroleum Engineer



101

101

101

101

101

101

101

101

101

101

101

101

101