

(SUBMIT IN TRIPLICATE)

Indian Agency Consolidated Ute

x		
	21	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee 14-20-604-83

Lease No. Ute Mountain

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
AUG 10 1960
U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8, 1960

Well No. 12 is located 550 ft. from N line and 1980 ft. from W line of sec. 21

NW/4 Sec. 21 31N 14W NMB56K
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde-Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

G. L.

The elevation of the ~~derrick floor~~ above sea level is 5727 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Two jts. 8-5/8" surface casing backed off while drilling 7-7/8" hole @ 379'.
Ran Spear and recovered all 8-5/8" casg.
Re-cemented 5 jts. of 8-5/8" casing at 107' w/80 sx + 2% CaCl.
Plug down 7 PM, 8/7/60. Good cement returns to surface.
Pressure tested 8-5/8" with 800# psi for 30 minutes; held ok.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Socony Mobil Oil Company, Inc.

Address P. O. Box 3371
Durango, Colorado

By P. M. Barry

Title Dist. Prod. Supt.

03/19/01

0000000000

RECEIVED 100-1030 2 16
FBI - MEMPHIS

