


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency

Allottee

Lease No.



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

June 22, 1959

Well No. 1012 is located 1012 ft. from S line and 600 ft. from E line of sec. 17
Section 17 (4 Sec. and Sec. No.) T-11-N (Twp.) R-11-W (Range) N-10-P-M (Meridian)
Verde Valley (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)


The elevation of the derrick floor above sea level is 2000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 2155'. Run logs runners-2155', "4" runners-2155',
Set 75 joints, 2155', of 1 1/2" casing at 2155 with 45 wt. cement. Top of the
cement at 2155'. Set two-stage cement collar at 2155 with 45 wt. cement.
Top of cement at 2155'.

Run in cable tools. Drilled cement 4/21/59. Tested for 2 hours with 200
pounds - pipe okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ARTIC OIL & GAS COMPANY

Address BOX 786

FARMINGTON, NEW MEXICO

ORIGINAL SIGNED BY JOE C. SALMON

By JOE C. SALMON
Title DEPUTY SUPERINTENDENT