

(SUBMIT IN TRIPLICATE)

Indian Agency Lincoln

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 1-40-601-32

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<b>II</b>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<b>RECEIVED</b>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) FARMINGTON NEW MEXICO

Ute-Indian No. 6-2

July 14

1959

Well No. 1 is located 1010 ft. from S line and 680 ft. from E line of sec. 17

NE/SE, Section 17,  
(1/4 Sec. and Sec. No.)

T-31N  
(Twp.)

R-11W  
(Range)

N. 27. N.  
(Meridian)

Verde Valley  
(Field)

San Juan County  
(County or Subdivision)


New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5052 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD = 2561, Ran logs: Top of Lower Gallup 2192'.  
Sand = oil frac. open hole 2155 - 2561 with 309 bbls. oil and 32,000 sand.  
Breakdown pressure 1200# to 900#. Treating Pressure = 1000#, I.S. 13 lbs.  
Loaded 75 jts. 2129' of 2" tbg. at 2410'.  
Installed Rods and Pump.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Aston Oil and Gas Company

Address Box # 786

Farmington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON  
Joe C. Salmon

Title District Superintendent