

(SUBMIT IN TRIPLICATE)

Indian Agency Lea, N.M.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 1-20-11-14

0		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL _____		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 100 ft. from S line and 100 ft. from E line of sec. 1
15/14 (1/4 Sec. and Sec. No.) 11-1 (Twp.) 1 (Range) 11-14 (Meridian)
Verde (Field) Lea (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded - 5/1/59. Set 3 joints (99.25') of 7 5/8" surface casing, cemented 10' at 10' interval. Tested casing with 100% pressure, 10 minutes, no leaks.

Drilled cement plug 5/1/59. Tested for 30 minutes with 100% pressure, no drop in pressure.

ILLECIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lea, N.M.
 Address 100 1st
Verde, N.M.

By ORIGINAL SIGNED BY JOE C. SALMON
 Title 1-20-11-14