



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Form Approved.

Land Office Santa Fe  
Lease No. \_\_\_\_\_  
Unit SP 077651  
Richardson

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

JUN 28 1963

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	.....

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 27, 1963

Well No. 7 is located 1621 ft. from N line and 1504 ft. from E line of sec. 15  
Section 15 (1/4 Sec. and Sec. No.) T-31N R-12W N.M.P.M.  
(Twp.) (Range) (Meridian)  
Wilcox, Dakota San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6267 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PROPOSED TO:

Pull 2 3/8" tubing and packer  
Set drillable Bridge plug at approximately 5500'  
Run new 4 1/2" casing, landing at approximately 5290'  
Cement casing and drill out with gas  
Re-run tubing without packer  
Put well back on production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AZTEC OIL & GAS COMPANY  
Address Drewer # 570  
Farmington, New Mexico  
By Joe C. Salton  
Title District Superintendent