

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **14-30-604-83**

Lease No. **Ute Mountain**

1			

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	APR 24 1959
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of 4 1/2" Liner	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 23, 1959

Well No. **1** is located **1900** ft. from **N** line and **530** ft. from **W** line of sec. **16**
N 1/4 Sec. 16 **31N** **14W** **N.M.P.M.**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Valley **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **9992** ft. **est.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5 1/2" cas. @ 2436'
T.B. 2346'

Ran 6 fts. 4 1/2" cas. O.D. 1 1/8" I.D. slotted 4- 1/2" per foot liner.
Top of 4 1/2" liner @ 2430' bottom of liner @ TD 2346'. Work completed 1-18-59.

Ref: U.S.G.S. Letter dated 4-21-59

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Magnolia Petroleum Company**
 Address **P. O. Box 2406**
Robbs, New Mexico

By **[Signature]**
 Title **District Superintendent**

