

(SUBMIT IN TRIPLICATE)

Indian Agency Santa Fe

Ute Mountain

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-151-16

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 14, 1957

h-A Ute Indian

Well No. / is located 1980 ft. from [N] line and 1980 ft. from [E] line of sec. 15

SW/NE, Section 15
(1/4 Sec. and Sec. No.)

T-31-N, R-15-W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Verde Gallup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5719 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 2026'. Perforated Tociro formation from 1942 to 1982 with 160 shots. Acidised with 500 gallons H.C.A., breakdown pressure 200#, final 0#. Sand oil frac with 42,000 gallons oil and 42,000# sand. Breakdown pressure 500#. Treating 450#, Final 250#, Injection Rate 43.5. Landed 1936' of 2 3/8" tubing at 1946. Installed rods and pump.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AZTEC OIL & GAS COMPANY

Address P. O. Box 786

Farrington, New Mexico

By Joe C. Salmon
Joe C. Salmon

Title District Superintendent

