

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Indian

•		17

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Ute Mountain Tribal
Contract No. 17-20-101-02
Lease No. 17-20-101-02

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
MAY 20 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. 1-17 is located 1920 ft. from N line and 530 ft. from E line of sec. 17
SW/4 NW/4 Sec. 17 T-31N R-14W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5926 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1- Ran 94.10 feet of 9 5/8", 32.3#, H-40 casing on July 6, 1957.
Landed at 95.95 feet D.F. Cemented w/80 sacks regular cement.
Cement circulated.

2- Ran 68 joints 2649' of 5 1/2", J-55, 15.5# casing on November 4, 1957.
Landed at 2643' R.K.B. Cemented w/80 sacks regular cement w/1" Cello-Flake/sack.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company
Address 1001 Bart Building
Dallas, Texas

By Paul J. Schote
Title Drilling Superintendent