

**(SUBMIT IN TRIPLICATE)**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency U.S.

Contract No. 14-20-604-81

Allottee -----

Co. Lease No. 231346

2			

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED

UTL INDIAN

Farmington, New Mexico Sept. 26, 1949-27 1957

Well No. 1 is located 382 ft. from N line and 382 ft. from W line of sec. 7 T. 1 N. R. 1 E. S. 1 E.

SW/L of SW/L

**T-31-N      R-14-N**

(34 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

## Gallup Verde

## San Juan

## New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5790 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

RECEIVED VERBAL APPROVAL 9/25/57.

9/26/57: Pulled rods and tubing. Set bridge plug at 2215' and dumped 2 sacks cement.

**Dry hole. Well temporarily abandoned.**



**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company Humble Oil & Refining Company

Address \_\_\_\_\_ Box 1268

**Farmington, New Mexico**

By J. C. Wiscley

Title Agent

