



APPROVED

JUL 26 1963

JERRY W. LONG  
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYBudget Bureau No. 42-R350.4.  
Approval expires 12-31-60.Indian Agency UteAllottee 604Lease No. 11-60-503-01

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

RECEIVED  
JUL 24 1963  
U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 22, 1963

Ute Indian  
Well No. 1 is located 302 ft. from S line and 302 ft. from W line of sec. 1SW SW Section 1 (1/4 Sec. and Sec. No.) T1N (Twp.) R1W (Range) R6E (Meridian)Barro Gullup (Field) San Juan (County or Subdivision) New Mexico (State or Territory)The elevation of the derrick floor above sea level is 5770 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

With your approval, Humble intends to permanently plug and abandon the subject well which has been temporarily abandoned since September, 1957.

Currently the well has a bridge plug set above perforations at 2215' with 16' (2 sacks) cement on top of the plug in the 5 1/2" production casing.

Humble intends to abandon the well with casing in place by placing 10 cu. cement at 1900' and 10 cu. cement at surface, fill casing with mud between the plugs and placing a regulation marker at surface.

2 5/8" CEMENT IN 8 5/8" - 5 1/2" ANNULUS

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining CompanyAddress P. O. Box 3182Durango, Colorado 81302By COPY (ORIGINAL SIGNED) D. V. EMERYTitle Dist. Engr.