

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency

Navajo - Ute Mtn Tribal

Allottee

Lease No. **14-20-600-3531**

SUNDRY NOTICES AND REPORTS ON WELLS

| | | | |
|---|----------|--|--|
| NOTICE OF INTENTION TO DRILL | | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | I | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
MAR 1 1963
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. **Navajo** **17-1 31-16** located **660** ft. from **[N]** line and **2030** ft. from **[W]** line of sec. **17**
March 20, 19 **63**

NE 1/4 **Sec. 17** **31-N** **16-W** **NMPN**
(U.S. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5698** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to a total depth of 1820'. No commercial oil or gas was found.
We propose to plug and abandon this well as follows:
Spot Cement Plug From T.D. to 1550'
Spot Cement Plug From 400' to 300'
Put 10 sk plug in top of 8 5/8" surface casing
Put in dry hole marker.
Hole was drilled with air to 1740'. Oil was used as circulating fluid from 1740 to T.D. Hole filled with oil.
These plugs were approved by Mr. P. T. McGrath with the U.S.G.S. in Farmington, New Mexico on 3-18-63. A subsequent report will be submitted after location is cleaned up.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Atlantic Refining Company**

Address **Box 2197**

Farmington, N.M.

By **B. J. Sartin**
Title **Drilling & Prod. Supervisor**