

(SUBMIT IN TRIPLICATE)

Indian Agency Ute

Indian Contract 14-20-604-81

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 231346

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

UTE INDIAN

Farmington, New Mexico December 4, 19 57

Well No. 3 is located 1980 ft. from SW line and 760 ft. from E line of sec. 7

SE 1/4 Section 7

T-31-N

R-11-W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Verde Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6067 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Used 841 bbls. Lead Oil to fracture well. Scrubbed and pumped 679 bbls. Lead oil.

On final 36 hour pumping test, well failed to produce.

162 bbls. Lead Oil lost in hole.

Verbal approval to abandon received 12-3-57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

By J. C. Winsley

Title Agent

