



(SUBMIT IN TRIPLICATE)  
**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Indian Agency \_\_\_\_\_  
Allottee \_\_\_\_\_  
Lease No. 1407 (00) 150

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

*Subsequent report of Csg. X*

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 4, 1962

Well No. 2 is located 200 ft. from N line and 1700 ft. from E line of sec. 7

14 Sec. and Sec. No. (Field) 200 (Twp.) 15 (Range) 100W (Meridian)  
San Juan (County or Subdivision) New Mexico (State or Territory)

RECEIVED

FEB 7 1963

The elevation of the derrick floor above sea level is 5000 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

Spudded at 11:00 a.m. 11-22-62. Drilled 12 1/2" hole to 108'. Ran 8 5/8" O.D. 24# J-55 casing set at 100.18'. Cemented with 80 sacks cement plus 2% CaCl<sub>2</sub>. Cement circulated. Job complete 5:30 p.m. 11-23-62.

W.O.C. & rig repair until 1:00 p.m. 11-26-62. Tested 8 5/8" csg. w/air OK. Started drilling cement with air at 2:00 p.m. 11-26-62.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The New Mexico Petroleum Co.

Address P.O. Box 1207

Albuquerque, N.M.

By B. J. Sartin

Title Drilling & Production Supervisor