



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved
Budget Bureau No. 42-R359.4.

Indian Agency _____
Navajo & Hopi Tribes

Allottee _____
Lease No. 11-20-600-3530

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 1, 1963

Well No. _____ is located _____ ft. from N line and 1710 ft. from E line of sec. 7

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field) (County or Subdivision) New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5642 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PERFORATION SUMMARY

Perforated 1607-1614 w/28 jets. on 12-11-62. Treated perms. w/40,000# 10/20 sand in 30,370 gal lease crude & 600 gal J-97. FBDP 2900 psi. Avg. treating press 1650 psi. Avg. rate 30.2 bpm. Job complete 9:00 am 12-12-62. Used 823 bbls. load oil.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____

Address _____

By B. J. Sartin

Title Drilling & Production Supervisor

