



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-B360.4
Approval expires 12-31-60.

Indian Agency Bureau

Allottee _____

Lease No. 24-00-000-0004
Co. Loc. No. 23452

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<u>APR 13 1950</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<u>1000</u>
NOTICE OF INTENTION TO ABANDON WELL		<u>Subsequent report of perforating and fracturing treatment</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Bureau Title Of Indians

Farmington, New Mexico

April 9, 19 50

Well No. 11 is located 1000 ft. from N line and 600 ft. from E line of sec. 20

Chimney Rock Oilfield

23N

27W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

SE 1/4 Section 10

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5224 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 7" hole 11:00 AM 3-23-50. Set 7" casing at 50' w/20 cu. yds. cement. Drilled into fresh water at 50', unable to blow hole dry. Mudded up and drilled 6-1/2" hole with mud to 607', casing point. Core #1 from 607' - 620', recovered 13' gray sandy shale and 10' light gray siliceous shale sand w/ 3-1/2" good oil show & 7-1/2" fair oil show. Core #2 from 620' - 627', recovered 3-1/2" sand w/fair oil show and 20-1/2" shale of which 8-1/2" had slight oil show. Ran electric logs. Set 4" casing at 724' w/70 cu. yds. oil oil cement. 700 3:15 PM, 4-2-50. Pumped plug down w/ 250 gal. H2O & oil. San Juan Bay 4" casing logs. Perforated 4" casing from 620' to 624' w/2 jet shots/24. Sand-oil flowed thru perforations w/20,000 gal. loose crude & 100 gal. oil. Ind rate of 27.4 BPM @ 11:00. Set 2" log. & 600'. San Juan to set pumping unit and pump back load oil.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shimko Oil & Refining Company

Address Box 1260

Farmington, New Mexico

By Harold H. Lilly
Title District Superintendent

