## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico



## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is com-

pleted. It should be signed and filed as a re- result of well repair, and other important instructions in the Rules and Regulations	port on Beginning Drilling Operations, operations, even though the work wa	Results of test of casing	shut-off, result of plug	ging of well,	
	Indicate Nature of Report by Cl	necking Below			
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TO CASING SHUT-OFF		T ON RING WELL		
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETI OPERATION	ON REPOR (Other)	T ON <b>Sand-oil</b> Fracture	x	
	November 1	8, 1954 <b>r</b>	armington, New	Mexico	
Following is a report on the work d	one and the results obtained under tn			•)	
El Paso Natural Gas Company (Company or Operator)			Hutchin Pool Unit		
Company Tools (Contractor)	, Well No	in the		ec <b>7</b> ,	
T <b>31N</b> , R <b>10V</b> , NMPM.,	Blanco	Pool, <b>San</b>	Juan	County.	
The Dates of this work were as follows:	11-4-54				
Notice of intention to do the work (was)	(was not) submitted on Form C-102 or	)(Cross out inco	rect words)	, 19,	
and approval of the proposed plan (was)	was not) obtained.				
DETAILI	ED ACCOUNT OF WORK DONE A	ND RESULTS OBTAIN	ED		
Total Depth 4995'.					
Sand-oil fracture Point 10,300# sand. BDF 900#, Natural gage 195 MCF.	Lookeut from 4773' -499 maximum pressure 1.000#,	5', with 12,950 Injection rate	gallons cil and 8.1 bbls./win.	L	
Witnessed by S. Schulenen (Name)	El Piso Natu	ral Gas Company	Petrolium	de incer	

I hereby certify that the information given above is true and complete to the best of my knowledge. Petroleum Engineer

Oil and Gas Inspector Dist. #3. (Title)

	- ARRESTON
OIL CONSERVATION C	OMINICA
OIL CONSERVATION	OFFICE
No. Conies Received	6
No. Copies Received	
The carry soul	
F. 132	NO.
nerator	
santa Fe	
1 Saire 1	
P. oration Office	The second secon
State Land Office	es .
U. S. G. S.	
Transporter	
	- Landing Care Control of the Contro
File	
The state of the s	22 V =