



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. W - 376014
Unit 2/2 Sec. 8

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
SEP 20 1960
GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent report of well stimulation</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 6 is located 1785 ft. from N line and 1470 ft. from E line of Sec. 1
48 1/4 Sec. 1 31-4 11-4 1470
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Under. Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

SEP 21 1960
FARMINGTON, N.M.
DIST. 3

The elevation of the derrick floor above sea level is 5074 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After 5-1/2" casing was run and cement set, perforated 7242-54, 7270-90, 7309-15, 7350-56, w/4 jets per ft. Free w/26,100 gals oil, 4700# sand pressures 3500-4000# 12 33 RPM landed off. Set plug at 7230. Perforated 7174-90, 7159-70 w/4 jets per ft. Free w/9200 gals oil, 4200# sand pressures 4000-4500#. CO to PSTD 7350 acidized w/500 gals HCl jet notched 5-1/2" cas. at 7265, 7254, 7244. Free w/62,000 gals oil 10,000 gals flush 44,000# sand pressures 3500-3800# 12 33 RPM. CO to PSTD 7350 landed 2" tubing at 7230 w/bit and sub perforated tubing 7232-38 w/24 holes, set knee tree, SI & blowing to clean up and test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Drawer 1186

Farmington, New Mexico

By J. A. Howell
District Superintendent

Title _____