

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | | |
|--|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. UNIT AGREEMENT NAME | |
| 2. NAME OF OPERATOR Solar Petroleum, Inc. | | 8. FARM OR LEASE NAME Navajo Tribe of Indians | |
| 3. ADDRESS OF OPERATOR Suite 2900, 1099-18th Street, Denver, Colorado 80202-1999 | | 9. WELL NO. 207 | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below) At surface 720' fNL & 710' fEL | | 10. FIELD AND POOL, OR WILDCAT Many Rocks Gallup | |
| 14. PERMIT NO. | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 12-31N-17W | |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5313' GR | | 12. COUNTY OR PARISH San Juan | |
| | | 18. STATE NM | |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

| | | |
|---------------------|--------------------------|----------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | FULL OR ALTEE CASING |
| FRACTURE TREAT | <input type="checkbox"/> | MULTIPLE COMPLETE |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | ABANDON* |
| REPAIR WELL | <input type="checkbox"/> | CHANGE PLANS |
| (Others) | | |

SUBSEQUENT REPORT OF :

| | | |
|---|--------------------------|-----------------|
| WATER SHUT-OFF | <input type="checkbox"/> | REPAIRING WELL |
| FRACTURE TREATMENT | <input type="checkbox"/> | ALTERING CASING |
| SHOOTING OR ACIDIZING | <input type="checkbox"/> | ABANDONMENT* |
| (Other) <u>Casing Integrity Attempt</u> | | |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. LOSS OF OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

8/26/88 - Could not pressure up. Brought packer up to $\pm 300'$, still leaking; hole above 300'.

Waiting on orders. Evaluating cost of plugging versus cost of repair.

RECEIVED
SEP 14 1968
OIL CON. DIV.
DIST. 2

14. I hereby certify that the foregoing is true and correct

SIGNED Stephanie L. Huntington
Stephanie L. Huntington

TITLE Engineering Technician

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ED FOR 95081
DATE 9/5/88

SEP 09 1964

DATE _____

FARMINGTON RESOURCE AREA

BY S/mv

***See Instructions on Reverse Side**