

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Navajo Tribal

Allottee _____

Lease No. _____
Contr. #14-20-600-3530

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 27

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

19

Chimney Rock
Well No. **# 14-6** is located **330** ft. from **[S]** line and **330** ft. from **[W]** line of sec. **6**
SW 1/4 Sec. 6 **31N** **16W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
unimproved **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5320** ft. **Ord. 530.5**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5/23/63 TD 1370. Drilled 7 7/8" hole. Ran logs. Ran 4 1/2 jts. (1376') 14 J-55 casing. Cemented with 125 sack cement with 3% Caclg. Shoe at 1375. Located top of cement at 520'. W. O. C. 8 hours and press. tested to 3500 PSI for 30 min. Hold OK. Preparing to perf.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Socony Mobil Oil Company, Inc.

Company _____

Address **P. O. Box 3371**

Durango, Colorado

By **M. J. Meyer** *sy RLP*

Title **Sr. Prod. Foreman**

U03S 5 Spgs 1 Plan 1 File 1