

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

Co. Lease No. 234971

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	AR 3 1 1959
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF ABANDONMENT	
	SUPPLEMENTARY WELL HISTORY	
	Supplemental report of perforating and fracturing treatment	2

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo Tribe #72

Farmington, New Mexico

March 29, 1959

Well No. 10 is located 300 ft. from N line and 640 ft. from E line of sec. 3
SW 1/4 of Section 3 31-N 17-W
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Osage Rock Gallup San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3200 ft. Gr.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded hole at 6:30 PM 3-20-59. Set 7" casing at 40' w/12 in. Reg. next cement.
 3-21-59: Run logs. Set 4" casing at 1046' w/10 in. 12 Casing Cement. Pumped plug down w/200 gal MSA and oil.
 3-23-59: Run Gamma Ray and Sillar logs. Set Perforated 4" casing from 990' - 1000' w/2 job shots/ft. Shot-oil fractured through perforations with 20,000 gal lease crude and 20,000 gal 2-100% FHL. Avg. Inj. rate 14.1 bbls/min at 1100'. Shut well in overnight.
 3-24-59: Set 2" tubing at 1007'. Run rods and pump. Installed pumping unit. Now pumping back lease oil.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Double Oil & Refining CompanyAddress Box 1216Farmington, New MexicoBy Russell M. LillyTitle Agent

