

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

December 31, 1985

Mr. T.C. Durham
BHP (Americas), Inc.
P.O. Box 977
Farmington, NM 87401

Re: Navajo Tribal Indians #4, P-05-31N-17W

Dear Mr. Durham:

The annual mechanical integrity test on the referenced water injection well indicated a casing leak. In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to inititate remedial action within 30 days. NMOCD Rule 708 states that the Division may require a demonstration of mechanical integrity prior to approving transfer of authority to inject. A mechanical integrity test well be required for the referenced well before approval of transfer of authority to inject will be granted.

Yours truly,

Carolyn J. Taplin

Field Respresentative

CJT/dj

xc: Prentiss Childs

UIC File
 Well File
 Operator File