

(SUBMIT IN TRIPLICATE)

Indian Agency Tonawanda

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 1140-1-1-15

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED

U. S. GEOLOGICAL SURVEY
ARMINSTER, NEW MEXICO

Well No. 1 is located 320 ft. from N line and 190 ft. from E line of sec. 4
1/4 Sec. and Sec. No. 1 (Twp.) 34 (Range) 1 (Meridian)
11 (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5366 ft. (surface of ground)

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

all was spudded on 4/24/59. Set 90' (3 jts.) of 10 3/4" casing at 90' with 90 sk. cement.

Tested casing with 500' pressure for 30 minutes, no leaks.

Drilled cement plug 6/21/59. Tested for 30 minutes with 500' pressure, no drop in pressure.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AMERICAN OIL COMPANY

Address Box 706

ORIGINAL SIGNED BY JOE C. SALMON

By JOE C. SALMON

Title MANAGER OIL & GAS DEPT

RECEIVED

1964

