


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SF - 078851  
Unit E/1 Sec. 4



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED  
SEP 9 1960

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO  
September 8, 1960

**Delhi-Stage**  
Well No. 7 is located 1850 ft. from N line and 1450 ft. from E line of sec. 4  
N 1/4 Sec. 4 31-N 11-W NMPS  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Unders. Dakota San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the Unders. Dakota above sea level is 6150 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 9-7/8" hole was drilled from 214' to 2985', set 7-5/8" 26.40# J-55 casing at 2985 w/200 cc cement w/4% gel. The casing was pressured to 800# for 30 min. After cement set, plug was drilled and hole was blown dry w/gas and remained dry. Drilling ahead resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Drawer 1196

Farmington, New Mexico

By J. B. Howell  
Title District Superintendent