



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 37 - 070051  
Unit 1/2 Sec. 4

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 13, 1960

**Delhi-Madge**  
Well No. 7 is located 1880 ft. from [N] line and 1450 ft. from [E] line of sec. 4  
NE 1/4 Sec. 4 11-3 11-N MMN  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Unders. Dakota Sandoz New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6160 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 7-5/8" casing a 6-3/4" hole was drilled w/gas to T.D. 7530. 1-1/2" 17# N-80 casing was set at 7530 w/250 sz 50/50 premix 4% gel 12-1/2# gilsonite per sz. followed w/30 sz latex cement. No temperature survey run, but cement came up hole high enough to kill gas flow from Mesaverde.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Drawer 1198

Farmington, New Mexico



By J. B. Howell  
Title Dist. Superintendent