


(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. 14-20-003-65



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 14, 1959

Well No. 6 is located 2310 ft. from N line and 1050 ft. from E line of sec. 5

NE 1/4 5 31N 17W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Chimney Rock San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 530 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 1/4" hole to 1140 - Set 4 1/2" 9.5# casing to 1090 with 35 sax. Fractured with 25,000# sand and 20,000 gallons lease crude oil. Ran tubing pump and rods and now pumping back load oil.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Robert L. Bayless

Address P.O. Box 15-1
Farmington, New Mexico

By R L Bayless
Title _____

1950