

District I

P.O. Box 1960, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources DepartmentOIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
DEPUTY OIL & GAS INSPECTOR
SANTA FE OFFICE
MAR 28 1995

Approved

PIT REMEDIATION AND CLOSURE REPORT

Operator: Phillips Petroleum Company Telephone: 505-599-3400Address: 5525 Hwy 64, NBU 3004, Farmington, NM 87401Facility Or: San Juan 32-7 Unit #10Well Name NLocation: Unit or Qtr/Qtr Sec SE SW Sec 32 T 32N R 7W County San JuanPit Type: Separator X Dehydrator Other Land Type: BLM State X Fee Other

RECEIVED
FEB - 8 1995
OIL CON. DIV.
DIST. 3

Pit Location: Pit dimensions: Length 20' width 20' depth 5'
(Attach diagram)
Reference: wellhead X other
Footage from reference: 55
Direction from reference: 66 Degrees X East North X
of
West South

Depth to Ground Water: 40'
(vertical distance from
contaminants to seasonal
highwater elevation of
ground water)

<u>X</u>	Less than 50 feet	(20 points)	
<u> </u>	50 ft to 99 feet	(10 points)	
<u> </u>	Greater than 100 feet	(0 points)	<u>20</u>

Wellhead Protection Area:
(less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources).

<u>X</u>	Yes	(20 points)	
<u> </u>	No	(0 points)	<u>0</u>

Distance to Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)

<u> </u>	Less than 200 feet	(20 points)	
<u> </u>	200 feet to 1000 feet	(10 points)	
<u>X</u>	Greater than 1000 feet	(0 points)	<u>0</u>

PITCFRM.WK3

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: n/a Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: n /a

Initial assessment of pit shows soil to be clean at the surface and
3' below pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 3' below pit bottom

Sample date 7-7-94 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 1.9

TPH ND

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 2/1/95 PRINTED NAME Ed Hasely

SIGNATURE Ed Hasely and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT/RE-ASSESSMENT SUMMARY

1994

ENVIROTECH, INC.

REVISED DATE: JULY 19, 1994

CLG

PIT NO.	WELL NAME	U-S-T-R	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE	GROUNDWATER ENCOUNTERED Sub-Surf Depth	SOIL TYPE	SAMPLE NO.	Organic Vapor Meter (PPM)	Total Recoverable Per. Hydro. (PPM)	EPA METHOD 8020 (PPB) METHOD 8030 PURGE AND-TRAP					STATUS
												Benzene	Toluene	Ethyl Benzene	Xylene	TOTAL BTEX	
PA210	SAN JUAN 32-7, #10	N23207	SEP	20	100	7-7-94	NO	SC	T1-5	1.5	ND						CLOSE
									T1-8	1.9	ND						
PA211	SAN JUAN 32-7, #52 PC	P323207	SEP	0	5000	7-7-94	NO	SC	T1-6	730	420	0	1110	9900	11800	22710	CLOSE
PA212	SAN JUAN 32-7, #8	A173107	SEP	20	100	7-7-94	NO	SG	T1-4	205	16400						REM ~ 4'
									T2-3	8.6	24						
PA213	SAN JUAN 32-7, #50	O343207	SEP/PROD	0	5000	7-7-94	NO	SC	T1-6	625	80	204	3480	1390	20690	25744	CLOSE
PA214	SAN JUAN 32-7, #88 DK	P343207	SEP	0	5000	7-7-94	NO	SC	T1-3	276	10						REM ~ 5'
									T1-6	36							
PA215	SAN JUAN 32-7, #46 NV	B343207	SEP/PROD	0	5000	7-7-94	NO	CH	T1-3	0	ND						CLOSE
									T1-6	2.7							
PA216	SAN JUAN 32-7, #46 PC	B343207	SEP/PROD	0	5000	7-8-94	NO	SW	T1-7	890	2880	5700	82100	16700	101100	205600	REM > 7'
PA217	SAN JUAN 32-7, #75	P273207	SEP/PROD	10	1000	7-8-94	NO	SC	T1-7	770	5720						REM ~ 7'
									T2-4	800	352	26	477	424	8390	9319	
PA218	SAN JUAN 32-7, #69 DK	A353207	SEP	0	5000	7-8-94	NO	SM	T1-4	10	ND						CLOSE
									T1-7	13							
PA219	SAN JUAN 32-7, #67 DK	L363207	SEP	0	5000	7-8-94	NO	SM	T1-4	20	ND						CLOSE
									T1-7	3							

PA 210

100-100000

JOB No. 23143
 DATE No. 1 of 1

DATE STARTED: _____
DATE FINISHED: 7/7/94
EMPO. SPCLT: CCF CLG
OPERATOR: DIAMFFCH
ASSISTANT: K.C.

LOCATION: LEASE: San Juan 32-7 WELL: 10 OD: 1050'S 1750'W (N)
SEC: 32 TWP: 32N RNG: 7W PM: NM CNTY: SJ ST: NM PIT: SEP.
LAND USE: range - base # E-503-9 elev. 6532
SURFACE CONDITIONS: dry earthen pit - stained

FIELD NOTES & REMARKS: PIT IS LOCATED APPROXIMATELY 55 FEET N66E OF WELLHEAD.
CLOSURE STD: 100 ppm GW=40'

RANKING SCOPE: 20

[illegible]

T1: light yellow brown sand w/ clay, slightly moist
 (has yellow + gray patches)
 6": gray sand w/ clay, no odor

close pit

TEST HOLE LOGS:

TH#:	SOIL TYPE:	SMPLE TYPE:	QVM, TCM
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			

pit bottom
SC GRB 1.5

SC GRB 1.9
TD=8'

SCALE

10/10/2011

FEET

SITE DIAGRAM

