

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY El Paso Natural Gas Company Box 997, Farmington, New Mexico
(Address)

LEASE Rosa Unit WELL NO. 29-32 UNIT H S 32 T 32N R 6W

DATE WORK PERFORMED 6-27-58 POOL Blanco M.V.

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Total Depth 6065'.

Ran 58 joints 5 1/2", 15.50#, J-55 liner (2400') set from 3662' to 6062' with 125 sacks regular cement, 125 sacks Formix, 12# gel, 1/8# Floccs/ak followed by 50 sacks regular cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 3662'.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)