

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

| | |
|--|--|
| <p>1. Type of Well GAS</p> <hr/> <p>2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY</p> <hr/> <p>3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <hr/> <p>4. Location of Well, Footage, Sec., T, R, M 1156' FSL 1800' FEL, Sec.36, T-31-N, R-10-W, NMPM, San Juan County</p> | <p>API # (assigned by OCD) 30-045-21097</p> <p>5. Lease Number</p> <p>6. State Oil&Gas Lease # B-10400-1</p> <p>7. Lease Name/Unit Name Atlantic D Com K</p> <p>8. Well No. 12</p> <p>9. Pool Name or Wildcat Blanco Pictures Cliffs</p> <p>10. Elevation:</p> |
|--|--|

RECEIVED
 DEC 4 1998
 OIL & GAS DIV.
 DIST. #3

| Type of Submission | Type of Action | |
|--|---|--|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion | <input type="checkbox"/> New Construction |
| <input type="checkbox"/> Final Abandonment | <input type="checkbox"/> Plugging Back | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> Water Shut off |
| | <input type="checkbox"/> Altering Casing | <input type="checkbox"/> Conversion to Injection |
| | <input checked="" type="checkbox"/> Other - restimulate | |

13. Describe Proposed or Completed Operations

It is intended to restimulate the Pictured Cliffs formation of the subject well in the following manner:

Clean out to plug back total depth at 3384'. Acidize and foam fracture treat the Pictured Cliffs zone. Clean out and return well to production.

SIGNATURE *John E. Perrin* (MDW) Regulatory Administrator November 30, 1998

TLW

(This space for State Use)

Approved by ORIGINAL SIGNED BY CHARLIE T. PERRIN Title DEPUTY OIL & GAS INSPECTOR, DIST. #3 Date DEC 4 1998