· · · · · · · · · · · · · · · · · · ·		7				
NO. OF COPIES RECEIVED	3	4				Form C-103 Supersedes Old
DISTRIBUTION		4				C-102 and C-103
SANTA FE	11-	NEW MI	EXICO OIL CONSI	ERVATION COMMISSION		Effective 1-1-65
FILE	1/-				_	
U.S.G.S.						5a. Indicate Type of Lease
LAND OFFICE					Ĺ	State X Fee
OPERATOR	1/	7				5. State Oil & Gas Lease No.
	- 	_				E- 5318 - 1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						
1.				-		7. Unit Agreement Name
OIL GAS WELL WEL	LX	OTHER-			ļ	
2. Name of Operator						8. Farm or Lease Name
EL DACO M	ATHDAI	GAS CO.				BROOKHAVEN COM
3. Address of Operator	ATUKAL	OAD CO:				9. Well No.
DON DOD	CADMIN	GTON, NEW MEX	XICO 87401			1A
BUX 990, 4. Location of Well	PARMIN	GION, NEW MEA	(100 07401			10. Field and Pool, or Wildcat
	-	120	Nonth	1060		BLANCO MESA VERDE
UNIT LETTER	,	120 FEET FROM	M THE NOTUL	LINE AND 1060 F	FEET FROM	TITITITITITITITITITITITITITITITITITITI
THE West	LINE, SECT	10N <u>16</u>	TOWNSHIP 31-N	RANGE10-W	нмрм.	
mmm	,,,,,,		ation (Show whether	DE RT CR ata 1		12. County
	//////					
		711111	6110' GL			San Juan
16.	Check	Appropriate Box	c To Indicate N	ature of Notice, Repor	rt or Oth	er Data
NOTI	CE OF I	INTENTION TO:		SUBSE	EQUENT	REPORT OF:
PERFORM REMEDIAL WORK	٦	PLU	G AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	7			COMMENCE DRILLING OPNS.	X	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHA	NGE PLANS	CASING TEST AND CEMENT JOB	. [7]	
7022 510 427411 41141112				OTHER		
OTHER						
		Operations (Clearly st	ate all pertinent det	tils, and give pertinent dates,	including e	estimated date of starting any propose
work) SEE RULE 1103.	ı					
1/1/70.	Spudde	ed well. Dril	lled surface	hole.		
1/4//0.	Spudde	M Well. Dill	rica sarraco	11010.		
1/5/30	D F	:-:-+- 0 5/01	1 72 7# U	10 surface casing	2101	set at 232'. Cemented
1/5/78:	Ran 5	joints 9 5/8	Γ , 32.3π , Π^{-1}	Surface Casing,	213 3	ont 12 hours: held
			irculated to	surface. Waited	on ceme	ent 12 hours; held
600#/30 r	ninutes	· .		. =		
						\
						N.
						5.
						<u> </u>
						e e e e e e e e e e e e e e e e e e e
					٠,	
18 I hereby certify that the	informati	on above is true and c	complete to the best	of my knowledge and belief.		
A A	A		•	-		
1/ H	L.	2.11		D 1111 01 1		1/1//70
SIGNED .	HI	2700	TITLE	Drilling Clerk		DATE 1/16/78
.) Ciano	a bor A	R. Kendrick				en e
APPROVED BY	A Dy A.	ALL MUNICIPAL SUR	TITLE			DATE

CONDITIONS OF APPROVAL, IF ANY: