

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Surveyed Old
C-102 and C-103
February 1977

1. Well Type (Check One)	Oil ☒ Gas ☐ Other ☐
2. Well No. & Name	11-5150-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Assignment Name
2. Name of Operator	San Juan 32-9 Unit
3. Address of Operator	San Juan 32-9 Unit
P. O. Box 990, Farmington, New Mexico 87401	89
4. Location of Well	10. Date of Notice, Report or Other Data
UNIT LETTER <u>E</u> <u>1675</u> FEET FROM THE <u>North</u> LINE AND <u>1188</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>31-N</u> RANGE <u>10-W</u> COUNTY <u>UNDE</u>	Undes P.C.
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
6055' GL	San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ABANDON CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☒	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion, if proposed work) SEE RULE 1103.

09-07-77 Spudded well. Drilled surface hole.
Ran 5 joints 8 5/8", 24#, K-55 surface casing, 205' set at 217'.
Cemented with 177 cu. ft. cement. Circulated to surface. Waited on cement 12 hours; held 600#/30 minutes.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. R. Kendrick TITLE Drilling Clerk DATE 9-8-77

Original Signed by A. R. Kendrick

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: