

FIELD PIT SITE ASSESSMENT FORM


GENERAL

SITE ASSESSMENT

MARKS

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 300° Footage from Wellhead 48
b) Length : 15 Width : 15 Depth : 3



Remarks :

Dry wash 150' due east of pit, No camera to have picture of
pit.

Completed By:

Lambert Garcia
Signature

7/20/94
Date