


State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088



PIT REMEDIATION AND CLOSURE REPORT

Operator: Williams Production Co. (Williams Field Services) Telephone: (801) 584-6361
Address: P.O. Box 58900, Salt Lake City, Utah 84158-0900
WellName: COX CANYON #19 (89343)
Location: Unit or Qtr/Qtr Sec C Sec 28 T 32N R 11W County San Juan
PitType Dehydrator
LandType Fee

Pit Location: Pit dimensions: length ft., width ft., depth ft.
(Attach diagram)

Reference: Wellhead

Footage from reference: 70 ft.

Direction from reference: 60 Degrees East of North

Depth To Ground Water:	Less than 50 feet	(20 points)	
(Vertical distance from	50 feet to 99 feet	(10 points)	
contaminants to seasonal	Greater than 100 feet	(0 points)	0
high water elevation of			
ground water)			

Wellhead Protection Area:	Yes	(20 points)	
(Less than 200 feet from a private	No	(0 points)	0
domestic water source, or; less than			
1000 feet from all other water sources)			

Distance To Surface Water:	Less than 200 feet	(20 points)	
(Horizontal distance to perennial	200 feet to 1,000 feet	(10 points)	
lakes, ponds, rivers, streams, creeks,	Greater than 1,000 feet	(0 points)	10
irrigation canals and ditches)			

Ranking Score (TOTAL POINTS): 10