

Date Remediation Started: 8/25/99

Date Completed: 8/25/99

Remediation Method: Excavation ☐  
(check all appropriate sections)

Approx. Cubic Yard

Landfarmed ☐

Insitu Bioremediation

Other ASSESSED

Remediation Location: Onsite ☐ Offsite(ie. landfarmed onsite,  
name and location of  
offsite facility)

## General Description Of Remedial Action:

Assessed site by excavating test pit adjacent to fiberglass tank installed in pit. Encountered BEDROCK at 1.5' bgs. Fill above bedrock had no odor or other evidence of hydrocarbon impact.

Ground Water Encountered: No

Final Pit: Sample location CC#19-A-TPFL-01

Closure Sampling:  
(if multiple samples, attach  
sample results and diagram  
of sample locations and  
depths)

Sample depth 1.5 feet

Sample date 8/25/99

Sample time 10:30

## Sample Result

Benzene (ppm) &lt;0.05

Total BTEX (ppm) &lt;0.05

Field Headspace (ppm)

TPH (ppm) 7.98

Ground Water Sample: No

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO  
THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 12-20-99

SIGNATURE  FOR WFSPRINTED NAME Mark Harvey for Williams Field Services  
AND TITLE