

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. USA-N-016746	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 720 So. Colorado Blvd., Denver, Colorado 80222		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850' F L and 1980' F L, Unit E		8. FARM OR LEASE NAME Horton	
14. PERMIT NO.		9. WELL NO.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6194' GL		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T31N, R9W	
		12. COUNTY OR PARISH 13. STATE San Juan NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

3-1-78 WOC 8+ hrs. after setting surface casing test to 600 psi. Held ok. Drilled 8 3/4" hole from 304' to 3600' KDB.

3-13-78 Ran 85 Jts 7" csg. Set @ 3600' w/450 sx smt. Pd @ 10:30 3-10-78. WOC 8 hrs. Drilled 6 1/4" hole from 3600' to 7,629' KDB.

3-18-78 Ran 91 Jts 4 1/2" csg. Set @ 7617' cmt w/ 475 sx cl B. Plug dn 1200 PSI @ 11:30 AM 3-18-78. Waiting on completion unit.

APR 24 1978

U.S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct.

SIGNED

*D. D. Myers*

TITLE: Div. Production Manager

DATE

4-17-78

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side