UNITED STATES

DEPARTMENT OF THE INTERIOR	5. LEASE SF 078507
GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS	IF INDIAN, ALLOTTEE OR TRIBE NAME UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 32-9 Unit 8. FARM OR LEASE NAME San Juan 32-9 Unit
1. oil gas well other	9. WELL NO. 3A
2. NAME OF OPERATOR EL PASO NATURAL GAS COMPANY 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco M.V.
Box 990, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-31-N, R-10-W
below.) AT SURFACE: 1815'S, 1450'E AT TOP PROD. INTERVAL:	N.M.P.M. 12. COUNTY OR PARISH 13. STATE San Juan New Mexico
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6572' GL
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and
3-12-78: Spudded well. Drilled surface hole. Ran surface casing, 213' set at 226'. Cement Circulated to surface. WOC 12 hours; hel	ted with 224 cu. ft. cement.