

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
990' FNLx 1540' FWL, Section 12,
AT SURFACE: T-31-N, R-14-W
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	Subsequent Report Of:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <u>Completion-Perf & Frac</u>	

5. LEASE
14-20-604-78

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ute Mountain Tribe

7. UNIT AGREEMENT NAME
Ute Mountain Tribal "J"

8. FARM OR LEASE NAME
Ute Mountain Tribal "J"

9. WELL NO.
30-045-22947

10. FIELD OR WILDCAT NAME
Undesignated Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
NE/4 NW/4 Section 12,
T-31-N, R-14-W

12. COUNTY OR PARISH
San Juan

13. STATE
NM

14. API NO.
30-045-22947

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6139' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion operations commenced on 5/31/78. Tripped in with tubing and bit. Cleaned out to 3151' PBD. Pressure tested casing to 3000 psi; held for 15 minutes - OK. Perforated 2886-2908. Fraced with 75,600 pounds sand and 37,800 gallons frac fluid. Tripped in with tubing. Cleaned out to 3130'. Landed tubing at 2900'. Swabbed well. Recovered 30 bbls. water per hour. Fluid level remained at 1200'. Swabbed 3 days. Fluid level 1600'. No shows of gas. Perforated 2785-2862. Fraced with 54,400 pounds sand and 27,200 gallons frac fluid. Swabbed well. No shows of gas.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED E. E. SVOBODA TITLE Area Adm. Supvr. DATE 8/11/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side

AUG 14 1978
U. S. GEOLOGICAL SURVEY
DENVER, COLO.